

JOB SITE CHECK LIST FOR BLAZELOK COATINGS

The following items are recommended for the application of Blazelok™ water based fire barrier coatings:

- Personal protection equipment
- SDS for the coating and all solvents and other cleanup materials
- Disposable gloves
- Correct spray tips - LTX 525 through LTX 531 (see Technical Data Sheet or material label)
- Airless sprayer with minimum .75 gallons per minute capacity (see Technical Data Sheet for recommended spray equipment)
- Electrical power and appropriate gauge extension cord
- Fuel and oil for gas powered sprayers
- Clean, empty 5 gallon pails for screening the coating into
- Door screen for screening paint
- 30 mesh machine and gun (if applicable) filters
- Power drill and mixer of appropriate size
- Large cardboard sheets for prep, spray testing and cleanup
- Drop cloths or poly sheeting
- Clean metal flashing or equivalent for making Thickness Test Panels (see Demilec's Coating Thickness Guide)
- Wet film gauge
- Electric heating pads as weather dictates (for 5 gallon pails)
- Portable fans to speed drying time
- Space heaters as required to create conditioned space (> 60°F)
- Hand tools for hose leaks, etc.
- Disposable paint brushes (plastic handles best to bend brush) for back brush areas
- 90 degree swivels and paint wand extensions as required
- Work lights as required
- Scaffolding, walk boards and safety rails as required
- Caliper for measuring the dried coating thickness on the Thickness Test Panels
- Permanent markers to mark the coating thickness on the Thickness Test Panels and areas needing touchup
- Cleanup rags
- 2 five gallon pails for cleanup
- 5 gallons of water for cleanup, warm if available
- Dish detergent for cleanup, 1 - 2 ounces
- Antifreeze solution for final rinse and storage in sprayer